









































STIFFENERS FOR VINYL PROFILES

 <p>HJ-7780-S 1.03 .843</p>	 <p>10286-S 1.736 0.957</p> <p>PATIO DOOR THRESHOLD</p>	 <p>HJ-8102-S 3.11 .265</p>	 <p>10247-S 0.984 0.540 0.820</p> <p>MEETING RAIL REINFORCING</p>	
 <p>4857-S 1.278 0.587</p> <p>MEETING RAIL REINFORCING</p>	 <p>6111-S 0.781 0.421</p>	 <p>6160-S 1.137</p>		
 <p>15388-S 0.743 0.577 1.116</p> <p>MEETING RAIL REINFORCING</p>	 <p>6222-S 1.236 1.268</p> <p>PATIO DOOR STIFFENER</p>	 <p>10586-S 1.438 0.492 R0.098</p> <p>PATIO DOOR ROLLER TRACK</p>		
 <p>6418-S 0.762 0.754</p>	 <p>6419-S 0.600 0.767</p>	 <p>15438-S 0.604 0.850 0.465</p> <p>BOTTOM RAIL REINFORCING</p>	 <p>6709-S 1.12 0.770</p> <p>PANEL REINFORCING</p>	 <p>15439-S 0.853 0.592 0.465 0.160</p> <p>SASH REINFORCING</p>
 <p>6801-S 1.070 0.832</p>	 <p>15429-S 0.915 0.718 0.248</p> <p>CASEMENT REINFORCING</p>	 <p>10509-S 0.870 0.410 0.553 0.699</p> <p>MEETING RAIL REINFORCING</p>	 <p>10942-S 0.690 0.300 0.450</p>	 <p>10585-S 0.846 0.173 150°</p> <p>SASH REINFORCING</p>
 <p>14835-S 1.115 1.08 0.306</p> <p>SINGLE HUNG FIXED RAIL REIN</p>	 <p>10251-S 0.798 1.080 0.728 0.411</p> <p>SINGLE HUNG FIXED RAIL REIN</p>	 <p>10246-S 1.050 0.200 0.100 0.500</p> <p>SASH REINFORCING</p>	 <p>10246-S 0.990 0.365 0.834 0.425</p> <p>SASH REINFORCING</p>	 <p>6754-H 1.140 0.455</p>
 <p>10245-S 1.000 0.437 0.050 0.435</p> <p>KEEPER REINFORCING</p>	 <p>10285-S 1.495 R0.094 0.682 0.733</p> <p>PATIO DOOR ROLLER TRACK</p>	 <p>10248-S 0.780 R0.050 0.568</p> <p>SCREEN ROLLER TRACK</p>	 <p>8875-S 1.000 0.158 0.435</p> <p>SASH REINFORCING</p>	 <p>8876-S 1.000 0.158 0.435</p> <p>SASH REINFORCING</p>
 <p>6801-S 1.115 0.812</p>	 <p>8877-S 1.000 0.435 0.337</p> <p>SASH REINFORCING</p>	 <p>8874-H 0.640 1.230 0.385</p> <p>LOCK RAIL REINFORCING</p>	 <p>11955-(SE4645) 1.010 0.769 0.860</p> <p>E.G. STILE REINFORCING</p>	 <p>11956-(S-050) 0.906 0.351 0.171</p> <p>KEEPER REINFORCING</p>
 <p>8882-S 1.115 0.977 0.305 0.415</p> <p>BOTTOM RAIL REINFORCING</p>	 <p>14361-S 1.030 0.465</p> <p>KEEPER REINFORCING</p>	 <p>8884-S 1.788 0.256 0.245 0.492</p> <p>ROLLER TRACK</p>	 <p>11954-(SE4646) 1.010 0.469 0.630 0.650</p> <p>TOP STILE REINFORCING</p>	 <p>11957-(S047) 0.820 0.370 0.650 0.281</p> <p>SASH REINFORCING</p>